

Oil Field Environmental Incident Summary

Incident: 20160118091245 **Date/Time of Notice:** 01/18/2016 09:12

Responsible Party: HUNT OIL COMPANY

Well Operator: HUNT OIL COMPANY

Well Name: SAUBER 1-17H

Field Name: PARSHALL

Well File #: 18076

Date Incident: 1/17/2016 **Time Incident:** 00:12

Facility ID Number:

County: MOUNTRAIL

Twp: 154

Rng: 89

Sec: 17

Qtr:

Location Description:

Submitted By: ALAN CLARK

Received By:

Contact Person: Justin Stuckmann
1900 NORTH AKARD STREET
DALLAS, TX 75201-2300

General Land Use: Well/Facility Site

Affected Medium: Well/Facility Soil

Distance Nearest Occupied Building: 1 Mile

Distance Nearest Water Well:

Type of Incident: Other

Release Contained in Dike: Yes - Within Dike

Reported to NRC: No

	Spilled	Units	Recovered	Units	Followup	Units
Oil						
Brine	170	Barrels	170	Barrels	170	barrels
Other						

Description of Other Released Contaminant:

Inspected:

Written Report Received: 4/11/2016

Clean Up Concluded: 1/23/2016

Risk Evaluation:

none

Areal Extent:

Potential Environmental Impacts:

none

Action Taken or Planned:

talked to truck driver to make sure load lines are completely sucked out dry.

Wastes Disposal Location:

Agencies Involved:

Updates

Date: 1/19/2016 **Status:** Reviewed - Assigned to Other Agency

Author: O'Gorman, Brian

Updated Oil Volume:

Updated Salt Water Volume:

Updated Other Volume:

Updated Other Contaminant

Notes:

According to the report, a release of brine water was contained to the facility site. NDIC retains oversight.